Troubleshooting Guide for WS2H, WS2HF, and WS3 Control Valves



WS2H, WS2HF, and WS3 Error Codes

Possible Errors		
Code	Description	
1001	No Encoder Pulses	
1002	Unexpected Stall, Main Drive	
1003	Run Time Too Long, Main Drive	
14001	Message Queue Full	
15003	Run Time Too Long, Bypass Drive	
15010	Run Time Too Short, Bypass Drive Could Not Drive Offline	
15011	Run Time Too Short, Bypass Drive Could Not Drive Online	
16001	Communication Lost With Unit 2	
16002	Communication Lost With Unit 3	
16003	Communication Lost With Unit 4	
18000	Reset Performed	
18001	Power Loss	
18002	Power Restored	
20001	Run time too long, AUX drive	
20002	Run time too short during unwind, AUX drive	
20011	Run time too short, AUX drive	
21XXX	System recovery from memory error	

Problem	Possible Cause	Solution
1. No Display on POD	 a. No power at electric outlet b. Control valve Power Adapter not plugged into outlet or power cord end not connected to PC board c. Improper power supply d. Poor connection between POD connector and PC Board. 	 a. Repair outlet or use working outlet b. Plug Power Adapter into outlet or connect power cord end to PC Board connection c. Verify proper voltage is being delivered to PC Board d. Check connector on POD, possible broken wire or terminal pin not inserted properly in connector. Clean pins on PC Board by plugging and unplugging the POD connector a few times to remove excess protective coating. e. Beplace Power Adapter
	f. Defective PC Board	f. Replace PC Board
2. POD does not display correct time of day	 a. Power Adapter plugged into electric outlet controlled by light switch b. Tripped breaker switch and/or tripped GFI c. Power outage d. Defective PC Board 	 a. Use uninterrupted outlet b. Reset breaker switch and/ or GFI switch c. Reset time of day d. Beplace PC Board
3 Display does not indicate	a. Bypass/ isolation valve in	a. Turn bypass/isolation handles to
that water is flowing. Refer to user instructions for how the display indicates water is flowing	by pass isolation valve in by pass positionb. Meter is not connected to meter connection on PC Board	 b. Connect meter to three pin connection labeled FLOW on PC Board
	c. Restricted/ stalled meter turbined. Meter wire not installed securely into three pin connector	 c. Remove meter and check for rotation or foreign material d. Verify meter cable wires are installed securely into three pin connector
	e. Defective meter	e. Replace meter
	f. Defective PC Board	f. Replace PC Board
 Control valve regenerates at wrong time of day 	a. Power outageb. Time of day not set correctlyc. Time of regeneration set incorrectly	a. Reset time of day.b. Reset to correct time of dayc. Reset regeneration time
	d. Control valve set at "on 0" (immediate regeneration)	d. Check programming setting and reset to dEL (for a delayed regen time)
5. Time of day flashes on and off	a. Power outage occurred	a. Test voltage of Lithium Coin Cell Battery (new battery 3.0v+, dead battery 2.75vdc). Replace battery if needed and reset time of day.
6. Control valve does not regenerate automatically when the REGEN button is depressed and held.	 a. Defective PC Board b. For the case of systems, another unit in regen would not allow another unit to go into regeneration 	a. Replace PC Board b. Wait for unit in regeneration to finish

Problem	Possible Cause	Solution
7. Control valve does not regenerate automatically but does regenerate when the REGEN button is depressed and held.	 a. Bypass/isolation valves in bypass position b. Meter is not connected to meter connection on PC Board c. Restricted/ stalled meter turbine d. Incorrect programming e. Meter wire not installed securely into three pin connectors f. Defective meter g. Defective PC Board 	 a. Turn bypass/isolation valve's handles to place in service position b. Connect meter to three pin connection labeled FLOW on PC Board c. Remove meter and check for rotation or foreign material d. Check for programming error e. Verify meter cable wires are installed securely into three pin connector labeled FLOW f. Replace meter g. Replace PC Board
8. Hard or untreated water is being delivered	 g. bolocitie i e bourd Check water quality directly at unit outlet 1) Water quality is good a) Bypass/isolation valves are open or faulty Water quality is poor a) Damaged seal/stack assembly b) Faulty riser tube or seal c) Control valve body type and piston type mis-matched Media is exhausted, water quality is poor a) Higher than anticipated water usage b) Meter not registering c) No regenerant or low level of regenerant in regenerant tank d) Control fails to draw in regenerant e) Water quality fluctuation f) Fouled media bed	 External Bypass Leak Fully close bypass/isolation valves or replace Internal Bypass Leak
9. Control valve uses too much regenerant	 a. Improper refill setting or refill flow control is not sized properly b. Improper program settings c. Control valve regenerates frequently 	 a. Check refill setting and check refill flow control for proper refill rate. b. Check program setting to make sure they are specific to the water quality and application needs c. Check for leaking fixtures that may be exhausting capacity or system is undersized

Problem	Possible Cause	Solution
10. Residual regenerant being delivered to service	a. Low water pressure	 a. Check incoming water pressure – water pressure must remain at minimum of 25 psi
	b. Plugged, fouled, or incorrect injector size	 b. Inspect and clean or replace injector, or replace injector with correct size for the application
	c. Restricted drain line	c. Check drain line for restrictions or debris and clean
	d. Damaged seal/ stack assembly or piston allowing leakage during draw	d. Check seal/stack assembly and piston for damage and replace
	e. Draw time too short f. Excessive refill g. Vacuum leak in draw line/elbow	e. Program proper draw time needed f. Program proper refill time needed g. Locate vacuum leak and fix
11. Excessive water in regenerant tank	 Tank is being overfilled a) Improper program settings b) Missing refill flow controller 	 Excess from fill cycle Verify program settings Visual inspection / measure volume output into container
	 Previous regenerant is not being drawn out 	2) See Troubleshooting Guide #12
12. Control valve fails to draw in regenerant	a. Injector is plugged	a. Remove injector and clean or replace
	b. Faulty regenerant pistonc. Regenerant line connection leakd. Drain line restriction or debris	 b. Replace regenerant piston c. Inspect regenerant line for air leak d. Inspect drain line and clean to
	causes excess back pressure	correct restriction
	e. Drain line too long or too high f. Low water pressure	 e. Shorten length and/or height f. Check incoming water pressure water pressure must remain at minimum of 25 psi
	g. Damaged seal/stack assembly	g. Inspect seal/stack assembly for damage and replace
13. Water running to drain	a. Power outage during regeneration or unit is currently in regeneration	a. Upon power being restored, control will finish the remaining regeneration time. Reset time of day.
	b. Damaged seal/stack assembly c. Piston assembly failure	b. Replace seal/stack assembly c. Replace piston assembly
	d. Drive cap assembly not tightened properly	d. Re-tighten the drive cap assembly

Problem	Possible Cause	Solution
14. Err – 1001 = Control unable to sense motor movement	a. Motor not inserted fully to engage pinion, motor wires broken or disconnected	a. Disconnect power, make sure motor is fully engaged, check for broken wires, make sure two pin connector on motor is connected to the two pin connection on the PC Board labeled REGEN. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
	b. PC Board not properly snapped into drive bracket	 b. Properly snap PC Board into drive bracket and then Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
	 c. Missing reduction gears d. Damaged or dirty reduction gear reflectors 	c. Replace missing gears d. Clean or replace reduction gear
	e. Faulty or dirty optics on back of PC board	e. Clean or replace PC Board
15. Err – 1002 = Control valve motor ran too short and was unable to find the next cycle position and stalled	a. Foreign material is lodged in control valve	 a. Open up control valve and pull out piston assembly and seal/ stack assembly for inspection. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position
	b. Mechanical binding	 b. Check piston and seal/ stack assembly, check reduction gears, check drive bracket and main drive gear interface. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. Check that pinion is not pressed up tight against motor.
	c. Main white drive gear too tight	 c. Loosen main drive gear. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. Verify free motion by rotating main drive gear
	d. Improper voltage being delivered to PC Board	 d. Verify that proper voltage is being supplied. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.

Problem	Possible Cause	Solution
16. Err – 1003 = Control valve motor ran too long and was unable to find the next cycle position	 a. Motor failure during a regeneration b. Foreign matter built up on piston and stack assemblies creating friction and drag enough to time out motor c. Drive bracket not snapped in properly and out of position enough that reduction gears and drive gear do not interface 	 a. Check motor connections then Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. b. Replace piston and stack assemblies. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. c. Snap drive bracket in properly then press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
17. Err - 14001 = Message queue full	a. LEAD PC Board did not receive a response from LAG units.	a. Press NEXT and REGEN buttons for > 3 seconds to resynchronize software with piston position.
18. Err -15003 = MAV or NHWBP valve motor ran too long and unable to find the proper park position	a. Control valve programmed for ALT A or NHWBP without having a motorized drive securely connected to the 2-pin terminal labeled "BYPASS" on the main PC Board	a. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. Re- program valve to proper setting
Motorized Alternating Valve = MAV No Hard Water Bypass = NHBP	 b. Poor wire connection c. Excess drag causing timeout before stall d. Motorized Bypass or MAV for NHBP motor not fully engaged with reduction gears 	 b. Remove power and check connection for Motorized Bypass or MAV for NHBP motor to PC Board two pin connection labeled BYPASS. Make sure wires in connector are inserted securely and no wires are broken. Clean pins on PC Board by plugging and unplugging the connector a few times to remove excess protective coating. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. c. Open Motorized Bypass or MAV for NHBP to check for obstructions d. Properly insert motor into casing, do not force into casing. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.

Problem	Possible Cause	Solution
19. Err – 15010 = Motorized Bypass or MAV for NHBP valve motor ran too short (stalled) while trying to drive off-line	a. Foreign material is lodged in Motorized Bypass or MAV for NHBP valve	a. Open up Motorized Bypass or MAV for NHBP and check for foreign material. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
Motorized Alternating Valve = MAV No Hard Water Bypass = NHBP	b. Mechanical binding	b. Check drive cap assembly or piston and seal/ stack assembly, check reduction gears, drive gear interface, and check Motorized Bypass or MAV for NHBP black drive pinion on motor. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position
20. Err – 15011 = Motorized Bypass or MAV for NHBP valve motor ran too short (stalled) while trying to drive online	a. Foreign material is lodged in Motorized Bypass or MAV for NHBP valve	a. Open up Motorized Bypass or MAV for NHBP and check for foreign material. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
Motorized Alternating Valve = MAV No Hard Water Bypass = NHBP	b. Mechanical binding	 b. Check drive cap assembly or piston and seal/ stack assembly, check reduction gears, drive gear interface, and check Motorized Bypass or MAV for NHBP black drive pinion on motor. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.

Problem	Possible Cause	Solution
 21. # of units error: Communications has been broken with the unit specified in the error message. These errors are logged as 16K series errors as follows: 16001: error with unit 2 16002: error with unit 3 16003: error with unit 4 16004: error with unit 5 16005: error with unit 5 16005: error with unit 6 16006: error with unit 7 	a. System is programmed for the wrong number of units or a LAG unit is in "error # of units" mode due to loss of power.	 Correct all errors on LAG units before attempting to reset error on LEAD unit Pressing any button while in the # of units error will enter the user into the setting screen. Adjust to the correct units for the system and press NEXT to exit the setup screen. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. Re- program valve to proper setting.
16007: error with unit 8 16008: error with unit 9 16009: error with unit 10 160010: error with unit 11 160011: error with unit 12 160012: error with unit 13 160013: error with unit 14 160014: error with unit 15 160015: error with unit 16	 b. Poor connection on PC Boards c. More than one unit has determined that it is the LEAD unit 	 b. Make sure wires in connector are inserted securely and no wires are broken. Clean pins on PC Board by plugging and unplugging the connector a few times to remove excess protective coating. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. c. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. Then re-program each valve to operate as a single individual unit. Re-program the control that is to be the LEAD unit and it will filter down the programming to the LAG units automatically.
22. Err – 18000 = Reset was performed, this error code will display in the diagnostics under the error log	a. Reset performed.	a. You can view dates and times resets were performed
23. Err – 18001 = Power loss, this error code will display in the diagnostics under error log	a. When power is lost a signal is sent to log the power loss	a. You can view dates and times when power outage occured
24. Err – 18002 = Power restored, this error code will display in the diagnostics under error log	a. When power is restored a signal is sent to log the power being restored	a. You can view dates and times when power outage occured

Problem	Possible Cause	Solution
25. Err – 20001 = AUX motor ran too long while trying to find proper park position.	a. Control valve programmed for NHBP or Separate Source without having a motorized drive securely connected to the 2-pin terminal labeled "AUX" on the main PC Board	a. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. Then re-program valve to proper setting
	b. Poor wire connection	 b. Remove power and check connection for MAV or NHBP motor to PC Board two pin connection labeled "AUX". Make sure wires in connector are inserted securely and no wires are broken. Clean pins on PC Board by plugging and unplugging the connector a few times to remove excess protective coating.
	c. Mechanical binding	c. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
	d. Motorized MAV for NHBP motor not fully engaged with reduction gears, should be flush top of gear cover.	d. Properly insert motor into casing, do not force into casing twist while inserting. Press NEXT and REGEN buttons for about 3 seconds to resynchronize
26. Err – 20002 = AUX motor ran too long during unwind.	a. When Aux motor ran into stall it did not unwind to relieve the stress on the pistons position.	a. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position.
27. Err – 20011 = Motorized MAV or NHBP valve motor ran too short (stalled) while trying to drive online	 a. Foreign material is lodged in MAV or NHBP valve b. Mechanical binding 	 a. Open MAV or NHBP and check for foreign material. Press NEXT and REGEN buttons for about 3 seconds to resynchronize software with piston position. b. Check main drive assembly, remove
		motor and be sure white gear turns freely.
28. Err – 21xxx = System auto recovery from memory location errors	a. Memory location verifications were corrected	a. You can view dates and times these occurred.

NOTES:

Revision History:

12/13/2022

Various grammatical and formatting changes throughout.

Page 9:

Updated solution to items 23 and 24.

Page 10:

Updated problem and possible cause to item 26.