


# WS2 MAV REV 2 • Flow Graphs




GPM	psi loss
5	0.0
10	0.0
15	0.1
20	0.1
25	0.2
30	0.2
35	0.3
40	0.4
45	0.5
50	0.6
55	0.8
60	0.9
65	1.1
70	1.2
75	1.4
80	1.6
85	1.8
90	2.1
95	2.3
100	2.5
105	2.8
110	3.1
115	3.4
120	3.7
125	4.0



# WS2 MAV REV 2 • Flow Graphs

GPM	psi loss
5	0.0
10	0.0
15	0.0
20	0.1
25	0.1
30	0.2
35	0.2
40	0.3
45	0.3
50	0.4
55	0.5
60	0.6
65	0.7
70	0.8
75	1.0
80	1.1
85	1.2
90	1.4
95	1.5
100	1.7
105	1.9
110	2.1
115	2.2
120	2.4
125	2.6



GPM	psi loss
5	0.0
10	0.0
15	0.1
20	0.2
25	0.3
30	0.4
35	0.5
40	0.7
45	0.8
50	1.0
55	1.3
60	1.5
65	1.8
70	2.0
75	2.3
80	2.7
85	3.0
90	3.4
95	3.8
100	4.2
105	4.6
110	5.1
115	5.5
120	6.0
125	6.5

